

**Earth Solutions NW<sub>LLC</sub>**

15365 NE 90<sup>th</sup> Street, Suite 100  
Redmond, WA 98052  
Main (425) 449-4704 | Fax (425) 449-4711  
www.esnw.com

**DAILY FIELD REPORT**

ESNW Rep. AJL	Project No. 2953.20	Page 1 of 1	Report No. 25v
Time On Site 11:45	Time Off Site 12:15	Date 9/28/20	Day of Week Monday
Travel Time 1 hr.		Weather 75°F, Sunny	

Project Name Westridge SF North (Vertical)	Job Location NE Discover Dr. & 9 <sup>th</sup> Ave NE, Issaquah	Client/Owner Polygon – WLH, Inc	
Contractor #1	Contact	Field Supervisor LAC	Reviewed JA 10/5
Contractor #2	Contact	Project Manager SHA	Reviewed

Are approved plans/permits on site?	Project No.	Permit No.
-------------------------------------	-------------	------------

Footing or Caisson Subgrade	Conditions Observed
Lot 67	Dense to very dense

As requested, ESNW rep was onsite to probe footing subgrade for lot 67. While on site, ESNW rep observed the following:

**Lot 67 Subgrade**

While onsite, ESNW rep observed that the contractor had brought lot 67 to footing grade. ESNW rep probed the excavated footing subgrade using a ½" diameter steel T-probe. ESNW rep observed dense to very dense soil conditions in the probed areas. These observed conditions are considered suitable for the support of the proposed SFR structure.

ESNW rep will return when requested.

Adrien Leland  
ESNW Assistant Field Manager

**NOTE: The ESNW rep. has observed only the footing and/or caisson excavations listed above. If any change in the subgrade conditions occur, we should be promptly notified.**